



# CERTIFICATE

It is to certify that E. M. R. S, Chandragiri has participated in the Fire safety and

Disaster Management Training organised by Orissa Fire and Emergency Service on dated - 19.03.2021

Asst. Fire Officer,  
Gajapati.

  
District Welfare Officer,  
Gajapati.



OFFICE OF THE ASSISTANT FIRE OFFICER  
PARALAKHEMUNDI, DIST. GAJAPATI

13

Memo No.

/PKI, FS

Date : 23.01.2012

To

The Principal,  
Ekalavya Model Residential School,  
Chandragiri, Dist. Gajapati, Odisha.

Sub : Suggestion regarding fire safety arrangements in Hostels and Administrative Block of EMRS,  
Chandagiri.

Ref. : Letter No.455/11 of EMRS, Chandragiri.

Sir,

I personally visited the Hostels and Administrative Block of your building regarding fire safety arrangements and found there are 3-DCP fire extinguishers of ABC type of one Kg. capacity are clamped one at each building and a water vat at the central location of the three buildings. But as per National Building Code it requires few more fire extinguishers. So I suggest how much fire extinguishers should be there at respective blocks.

I. Boys Hostel :

- i. Ground floor : One DCP fire extinguisher of at least 5Kg capacity and one water type fire extinguisher of 9 liter water capacity.
- ii. 1<sup>st</sup> Floor : Two nos of DCP fire extinguishers of at least 5Kg. capacity & one water type fire extinguisher of 9 liters water capacity.

II. Girls Hostel :

- i. Ground floor : One DCP fire extinguisher of at least 5Kg capacity and one water type fire extinguisher of 9 liter water capacity.
- ii. 1<sup>st</sup> Floor : Two nos of DCP fire extinguishers of at least 5Kg. capacity & one water type fire extinguisher of 9 liters water capacity.

III. Administrative Block :

There should be four (3 nos DCP + 1 Water type) fire extinguishers should be there as follows :

- i. One DCP fire extinguisher near Principal Office.
- ii. One DCP fire extinguisher of ABC type near Chemistry Lab.
- iii. One DCP fire extinguisher near Physics Lab and
- iv. One at the centre of the wall of class rooms opposite to the Principal Office.

All the fire extinguishers should be clamped suitably at suitable place.

*Sd/-*  
Officer-in-Charge

Paralakhemundi, Fire Station

Memo No. \_\_\_\_\_/PKI, FS

Dt. \_\_\_\_\_ 01.2012

Copy submitted to the Collector & DM, Gajapati for kind information.

*Sd/-*  
Officer-in-Charge

Paralakhemundi, Fire Station

Memo No. 113 /PKI, FS

Dt. 23.01.2012

Copy submitted to PA, ITDA, Paralakhemundi, Gajapati for kind information and necessary action.

*Abh. 01*  
*Sd/-*  
Officer-in-Charge

Paralakhemundi, Fire Station

Memo No. \_\_\_\_\_/PKI, FS

Dt. \_\_\_\_\_ 01.2012

Copy submitted to the I/C Chief Fire Officer, Odisha, Cuttack for kind information.

*Sd/-*  
Officer-in-Charge

Paralakhemundi, Fire Station

*11/11/12*  
*01-04-12*